TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R323X - LITE X-OVER HOLSTER TROUSER

25.02.2016

	XS	S	M	L	XL	2XL	3XL	4XL	5XL
Waist in inches*	30	32	34	36	38	40	42	44	46
Waist in cm*	76	84	86	91	96	102	107	112	117
German clothing size	46	48	50	52	54	56	58	60	62

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm